

WCRWG Status Report: 2021-08-25

Notes and Updates since last report

1. Previous reports can be found at <http://wcrwg.co.za/category/status-report/>

Donations received since last report.

None

General requirements: upgrade and maintenance program

1. Cash donations
2. High quality N-type male and female connectors for ½" heliax
3. VHF and UHF ferrite circulators.

Repeater Information and Status

Repeater status is usually one of **DOWN**, **Operational** or **Testing**.

| 145.575 | <i>Bottelary</i> |
|-----------------------------------|--|
| Status | Operational |
| Frequencies and Tones | Output: 145.575 / Input: 144.975 (ZU9DBI_C) |
| Mode | D*STAR (6K0F7W - GMSK) |
| Faults Reported | None |
| Site specific requirements | Set RPT1 as ZU9DBI_C, RPT2 as ZU9DBI_G – replace _ with a space. |
| Links | Internet – ZU9DBI_G gateway – default linked to TG655 |
| Notes | The repeater has a 3 minute transmit timer with an approximate 30 second lockout penalty. This is a factory setting in the controller. Users are advised to set a transmit timeout in their radios of less than 3 minutes. |

| 145.600 | <i>Hanskop (Sir Lowry's Pass)</i> |
|-----------------------------------|--|
| Status | Operational |
| Frequencies and Tones | Output: 145.600 (88.5) / Input: 145.000 (88.5) |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site specific requirements | None |
| Links | Link to Jonaskop/145.675 operational |
| Notes | DTMF codes are published on the WCRWG website |

| 145.625 | <i>Piketberg</i> |
|-----------------------------------|--|
| Status | Operational |
| Frequencies and Tones | Output: 145.625 (88.5) / Input: 145.025 (88.5) |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site specific requirements | None |
| Links | Link to Hawequas/145.650 operational |
| Notes | DTMF codes are published on the WCRWG website |

| | |
|-----------------------------------|--|
| 145.650 | <i>Hawequas (Du Toitskloof Pass)</i> |
| Status | Operational |
| Frequencies and Tones | Output: 145.650 (88.5) / Input: 145.050 (88.5) |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | Big power spikes and outages reported. Audio problem from controller to VHF repeater. No CTCSS output as a result of commercial breakthrough. External temperature sensor faulty. |
| Site-specific requirements | None |
| Links | 1. Link to Hanskop/434.600 operational 2. Link to Piketberg/145.625 operational |
| Notes | DTMF codes are published on the WCRWG website |

| | |
|-----------------------------------|---|
| 145.650 | <i>Riversdale</i> |
| Status | Operational |
| Frequencies and Tones | Output: 145.650 / Input: 145.050 |
| Mode | Analogue FM (16K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | 3. Link to Jonaskop/145.675 operational 4. Link to George/145.700 disconnected due to low audio. |
| Notes | |

| | |
|-----------------------------------|---|
| 145.675 | <i>Jonaskop (Villiersdorp)</i> |
| Status | Partially operational |
| Frequencies and Tones | Output: 145.675 (88.5) / Input: 145.075 (88.5) |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | 1. Link to Hanskop/145.600 down 2. Link to Riversdale/145.650 down |
| Notes | DTMF codes are published on the WCRWG website |

| | |
|-----------------------------------|--|
| 145.700 | Constantiaberg |
| Status | Operational |
| Frequencies and Tones | Output: 145.700 (88.5) / Input: 145.100 (88.5) |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | None |
| Notes | Antenna upgrade being planned. |

| | |
|-----------------------------------|--|
| 145.700 | George |
| Status | Operational |
| Frequencies and Tones | Output: 145.700 / Input: 145.100 |
| Mode | Analogue FM (16K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | Linked via 438.725MHz repeater at Dana Bay |
| Notes | DTMF codes are published on the WCRWG website. |

| | |
|-----------------------------------|----------------------------------|
| 145.725 | Hermanus (Onrusberg) |
| Status | Operational |
| Frequencies and Tones | Output: 145.725 / Input: 145.125 |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | Link to Hanskop. |
| Notes | |

| | |
|-----------------------------------|---|
| 145.750 | Kanonkop (Tygerberg) |
| Status | Operational |
| Frequencies and Tones | Output: 145.750 (88.5) / Input: 145.150 |
| Mode | Analogue FM (16K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | None |
| Notes | |

| | |
|-----------------------------------|--|
| 434.650 | <i>Hanskop (Sir Lowry's Pass)</i> |
| Status | Operational |
| Frequencies and Tones | Output: 434.650 / Input: 433.050 |
| Mode | Analogue FM-N (11K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | 1. Link to Hawequas/145.650 operational |
| Notes | |

| | |
|-----------------------------------|---|
| 434.625 | <i>Kanonkop (Tygerberg)</i> |
| Status | Operational |
| Frequencies and Tones | Output: 434.625 (88.5) / Input: 433.025 |
| Mode | Analogue FM (16K0F3E) |
| Faults Reported | IRLP/Echolink currently disabled pending computer repairs. |
| Site-specific requirements | None |
| Links | 1. IRLP node 8535 2. Echolink node 796398 (ZU9DCM-R), using EchoIRLP modification. |
| Notes | Dial-out to other Echolink nodes requires the use of a dial prefix, currently *0 (star-zero), as it is an add-on to IRLP. The disconnect code for a call is '73' – use this for both Echolink and IRLP calls. |

| | |
|-----------------------------------|----------------------------------|
| 438.725 | <i>Dana Bay</i> |
| Status | Operational |
| Frequencies and Tones | Output: 438.725 / Input: 431.125 |
| Mode | Analogue FM (16K0F3E) |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | 1. Linked to George, Riversdale |
| Notes | |

| | |
|-----------------------------------|--|
| 438.300 | <i>Bottelary</i> |
| Status | Operational |
| Frequencies and Tones | Output: 438.300 / Input: 430.700 |
| Mode | 1 - DMR (7K60FXD/E - 4FSK) 2 - D*STAR (6K0F7W – GMSK) 3 – Yaesu System Fusion (11K2F7W - C4FM) |
| Faults Reported | None |
| Site specific requirements | For D*STAR, set RPT1 as ZU9DMR_B, RPT2 as ZU9DMR_G – replace “_” character with a space. |
| Links | Internet – ZU9DMR_G gateway |
| Notes | DMR ID 655101 The repeater will autodetect modes as long as no other mode is operational. |

| | |
|-----------------------------------|----------------------------------|
| 438.350 | <i>Helderberg DMR</i> |
| Status | Operational |
| Frequencies and Tones | Output: 438.350 / Input: 430.750 |
| Mode | DMR (7K60FXD/E - 4FSK) |
| Faults Reported | None |
| Site specific requirements | None |
| Links | None |
| Notes | DMR ID 655102 |

| | |
|-----------------------------------|----------------------------------|
| 438.400 | <i>Noon Gun DMR</i> |
| Status | Operational |
| Frequencies and Tones | Output: 438.400 / Input: 430.800 |
| Mode | DMR (7K60FXD/E - 4FSK) |
| Faults Reported | None |
| Site specific requirements | None |
| Links | None |
| Notes | DMR ID 655103 |

| | |
|-----------------------------------|-------------------------------------|
| ZS0DCC | <i>Helderberg Digipeater</i> |
| Status | Operational |
| Frequencies and Tones | Output: 144.800 / Input: 144.800 |
| Mode | Digital FM-N (11K0F2D) AFSK |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | None |
| Notes | None |

| | |
|-----------------------------------|---|
| ZS1TWO | <i>2-Meter Beacon (Lower Burg St)</i> |
| Status | Operational |
| Frequencies and Tones | 144.435 |
| Mode | CW |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | None |
| Notes | 20W into a 5-element beam antenna pointing around 50 degrees (NE) |

| | |
|-----------------------------------|-------------------------------------|
| ZS1SIX | <i>6-Meter Beacon (CPUT)</i> |
| Status | Operational |
| Frequencies and Tones | 50.080 |
| Mode | FSK |
| Faults Reported | None |
| Site-specific requirements | None |
| Links | None |
| Notes | None |

Send fault reports via e-mail to: wc-repeater-fault@googlegroups.com

To receive the weekly report direct via e-mail, subscribe to: wc-repeater-announcements@googlegroups.com. You can subscribe by sending an e-mail message to wc-repeater-announcements+subscribe@googlegroups.com.

The WCRWG has a new website packed full of information on all the repeaters and detailed reports of activities. You can access this website via the link <http://www.wcrwg.co.za/>

Any notes, updates, incidents or donations are to be sent by e-mail to 'reports@wcrwg.co.za' to reach that mailbox no later than 16:00 SAST on the Tuesday of publication of the report. Any information received after that will be held over to the following report.

Account Information

Account Name: Western Cape Repeater Working Group (WCRWG)

Bank: FNB

Account type: Cheque

Account number: 62338034937

Branch code: 250655 (Electronic payments)

Branch code: 200612 (Counter deposits)